
OPTICAL STORAGE APPARATUS AND ABNORMALITY...
Miyamoto et al.
Greer, Burns & Crain, Ltd. (Patrick Burns)
Ref. No. 3408.68347
Sheet 1 of 13 (312) 360 0080

FIG. 1



OPTICAL STORAGE APPARATUS AND ABNORMALITY...
Miyamoto et al.
Greer, Burns & Crain, Ltd. (Patrick Burns)
Ref. No. 3408.68347
Sheet 2 of 13 (312) 360 0080

FIG. 2







FIG. 3





OPTICAL STORAGE APPARATUS AND ABNORMALITY...
Miyamoto et al.
Greer, Burns & Crain, Ltd. (Patrick Burns)
Ref. No. 3408.68347
Sheet 4 of 13 (312) 360 0080

FIG. 5



OPTICAL STORAGE APPARATUS AND ABNORMALITY...
Miyamoto et al.
Greer, Burns & Crain, Ltd. (Patrick Burns)
Ref. No. 3408.68347
Sheet 5 of 13 (312) 360 0080

FIG. 6





FIG. 7






FIG. 8

OPTICAL STORAGE APPARATUS AND ABNORMALITY...
Miyamoto et al.
Greer, Burns & Crain, Ltd. (Patrick Burns)
Ref. No. 3408.68347
Sheet 7 of 13 (312) 360 0080









FIG. 10





OPTICAL STORAGE APPARATUS AND ABNORMALITY...
Miyamoto et al.
Greer, Burns & Crain, Ltd. (Patrick Burns)
Ref. No. 3408.68347
Sheet 8 of 13 (312) 360 0080

FIG. 11












FIG. 16



